

PORSE

11.3.31.1.1 V31

COR



**PORT OF PORTLAND**

December 21, 2001

Mr. Rod Struck  
Oregon Department of Environmental Quality  
Voluntary Cleanup Program  
2020 SW Fourth Avenue, Suite 400  
Portland, Oregon 97201-4987

**Re: Marine Terminal 1 South Site  
Monitoring Well Installation and Groundwater Sampling Report  
ECSI No. 2642**

Dear Mr. Struck:

The Port of Portland (Port) has prepared the Monitoring Well Installation and Groundwater Sampling Report for the Marine Terminal 1 (T1) South Site. Seven monitoring wells were installed and sampled in accordance with the Oregon Department of Environmental Quality (DEQ) approved T1 South Work Plan Addendum No. 2 for Groundwater Monitoring, dated August 1, 2001. The attached report documents the monitoring well installation and groundwater sampling results, as well as additional information related to the beneficial use of groundwater requested by DEQ in review comments on the T1 South Remedial Investigation Report.

Please contact me at (503) 944-7533 with any questions.

Sincerely,

Joe Mollusky  
Environmental Project Manager  
Property and Development Services

Attachment

cc: Bill Bach, Port (w/o attachment)  
Jeff Bachrach, Ramis Crew Corrigan & Bachrach (w/o attachment)  
Taku Fuji, Hart Crowser  
Tim Ralston, Ralston Investments  
Guy Tanz, Hahn and Associates (w/o attachment)

**USEPA SF**



**1286571**

Mr. Rod Struck  
December 21, 2001  
Page 2

bcc: David Ashton, Port (w/o attachment)  
Trey Harbert, Port (w/o attachment)  
Nancy Murray, Port (w/o attachment)  
Bob Teeter, Port

POPT1S601374